


# Measurements on a Crybaby Shell

Dimensions taken from unknown vintage Crybaby shell that's what I had to measure. Expect variations on other shells and use this as a guide only.

## Hole Locations relative to front treadle screw location



## Approximate Maximum PCB Dimensions

